



BROCKPORT

Central School District

Business Offices • 40 Allen Street, Brockport, New York 14420 – 2296 • Phone (585) 637-1820 • Fax: (585) 637-1829

Darrin N. Winkley

Assistant Superintendent for Business

Brockport Central School District Lead Remediation - Action Plan – September 30, 2021

In May of 2021 the Brockport Central School District contracted with Labella Associates to collect first draw samples from outlets of potential drinking water sources throughout five school buildings and 6 auxiliary buildings.

A total of 369 samples were taken district wide. Of those 369 samples, 33 were found to have lead levels above the action level of 15 PPB (Parts per Billion). 10 of the 33 were retested and results were below the action level and required no further action.

Additional testing was conducted on 17 of the remaining 23 outlets during June and July 2021. Six of the sources were not retested as these areas were determined to not be potential sources of drinking water and have been labeled “Not for Drinking” at the outlet. These six fixtures were located at the High School (room 129 taps 1, 2 and 3 and room 193 utility tap), a Concession stand hose bib and an outside hose bib at the District Administration Building.

Of the 17 sources retested in June and July 2021, 7 were at the Senior High School, 1 at the Fred Hill School, 3 at the Barclay School, 1 at the Ginther School, 2 at the Concession Stand and 3 at the Oliver Middle School. 14 of the 17 test sites were determined not be potential sources of drinking water and have been labeled “Not for Drinking” at the outlet and are listed in the chart below.

Building	Room #	Fixture	Action
Barclay	120	Office 120 sink	Fixture labeled do not drink
Barclay	120	Office Restroom 120 sink	Fixture labeled do not drink
Barclay	Exterior 606	Exterior hose bib	Fixture labeled do not drink
Concession Stand	Exterior by bathrooms	Exterior hose bib	Fixture labeled do not drink
Concession Stand	Exterior by bathrooms	Exterior hose bib	Fixture labeled do not drink
Ginther	505 Men’s bathroom	Room 505 Sink	Fixture labeled do not drink
High School	013	Classroom 013 Sink	Fixture labeled do not drink
High School	014	Classroom 014 Sink	Fixture labeled do not drink
High School	138G	Girl's Restroom 138G Tap	Fixture labeled do not drink
High School	197	Girl's Locker Room 197 Left Sink	Fixture labeled do not drink
High School	197	Girl's Locker Room 197 Right Sink	Fixture labeled do not drink
Oliver Middle School	153	Classroom 153 Right Sink	Fixture labeled do not drink
Oliver Middle School	101A	Gym Office 101A Sink	Fixture labeled do not drink
Oliver Middle School	101C	Gym Office 101C Sink	Fixture labeled do not drink

Remediation measures were taken at the three remaining locations and the fixtures were retested.

- **High School Nurse's office room C** had filter added to the supply line and fixture retest was less than 5.0 PPB.
- **High School Nurse's office room D** had filter added to the supply line and fixture retest was less than 5.0 PPB.
- **Hill School Room 119 Pot filler 1** had the faucet replaced and fixture retest was less than 5.0 PPB